



- _1: Hook Climbing Hook into Lashing Chain
 - _2: Pull back Lever & pre tension Lashing Chain
 - _3: Swing in lashing chain towards Lever Nose
 - _4: Hook Lashing Chain in on Lever Nose
 - _5: Pull Down Lever
 - _6: Release Climbing Hook
- Repeat steps 1-6 until Lashing Chain is tight and secure.**
- _7: Secure Lever.

00	First Issue	26/10/18	JGU	BVQ	XS
Rev.	Discription of issue	Date	Name	Checked	Approved
Basic Tolerances for linear and angular dimensions sizes, free tol. acc. to DIN 2768-v T1, 2 Basic Tolerances for Welded constructions DIN 8570 T1,3 Castings DIN 1683A Shape and position tolerances according to DIN 1101 - weld symbols according to ISO 2553		Surface roughness acc. to ISO R1302 Ra µm:		Total Weight: N/A	
Ownership of International Lashing Systems n.v.duplication or disclosure to third parties in any form whatsoever, is prohibited without written permission of the owner.		Scale 1 : 12	Format: A3	Title: LASHING LEVER CHAIN TENSIONING INSTRUCTIONS	
		Client:		Rev.	
		Drawn by jori	Drawing n°.: LEVER INSTRUCTIONS		
		Check. by			
		Date: 25/10/2018	Part of:	Project n°:	

